

Water Source Type	Sample ID	Location Description	Lead Concentrations (in ppb)						
			6/26/16 1st draw	6/26/16 flush	7/19/16 1st draw	7/19/16 flush	8/10/16 1st draw	8/10/16 flush	11/2/16 1st draw
sink	RL-A1	Building A, Room 1 (KG)	9.99		14.6	2.14			12.7
sink	RL-A2	Building A, Room 2 (KG)	21.0		31.5	2.32			19.4
sink	RL-Akinder	Building A, KG restroom	17.5	3.98					
water fountain	RL-AFountain	Building A hallway	5.22						
sink	RL-AK	Building A kitchenette	3.17						
sink	RL-AG1	Building A, girls' restroom sink #1 (north/left)	1.14						
sink	RL-AB2	Building A, boys' restroom sink #2 (left center)	0.79						
water fountain	RL-BE down	Building B, east side, downstairs	2.69						
sink	RL-BEG1	Building B, east side, girls' restroom sink #1	1.01						
sink	RL-BEB1	Building B, east side, boys' restroom sink #1	1.22						
water fountain	RL-BEup	Building B, east side, upstairs	8.49						
sink	RL-B Utility	Building B, east side, upstairs utility sink							13.7
sink	RL-B7	Building B, southeast side Room 7 (Carrie's Room)							3.07
sink	RL-BEMary	Building B, northeast side, Room 8 (Mary's Room)	4.37						
sink	RL-BWG1	Building B, west side, girls' restroom sink #1	13.2						
water fountain	RL-BW down	Building B, west side, downstairs					35.0	11.3	0.766
sink	RL-BWB1	Building B, west side, boys' restroom sink #1	1150		89.4	5.45			51.0
sink	RL-BWB2	Building B, west side, boys' restroom sink #2			60.7	6			37.8
sink	RL-B11E	Building B, Room 11, east of interior door	32		40.6	21.5			2.17
sink	RL-B11W	Building B, Room 11, west of interior door	22		815	8.1			
sink	RL-BWup	Building B, west side, upstairs	3.55						